

BUILDING SAFETY CERTIFICATERef No. 577 / Building Safety CertificateDated: 11 / 8 /2026

It is certified that the existing building of, Subhash Chandra Bose Academy at Nathuwawala Raipur Gullarghati Road, Dehradun, Uttarakhand is having block(s)/ Floor(s) as per details below:

Detail of Block(s) in school	Block (A)	Block (B)	Block (C)	Block (D)	Block (E)	Block (F)
No. of Floor(s) in the Block	4	1 Basement 4 Floor	-	-	-	-

The building is owned/occupied by Subhash Chandra Bose Academy at Nathuwawala Raipur Gullarghati Road, Dehradun, Uttarakhand have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the Sub Divisional Engineer, Temporary Division, PWD Rishikesh, Dehradun on 10/08/2026 in the presence of Mr. Anil Semlty Admin of the school and that the building / premises is fit for occupancy for running school with effect from 10/08/2026 for a period of two year in accordance with rule and subject to compliance of the specific conditions as appended.

1. In case any addition/alteration or expansion and modifications to this building is to be carried out, the same be carried out under the supervision of a qualified Engineer and this certificate may be re-obtained after the completion from the undersigned.
2. Approved Design and Drawing of Building not provided by school administration at the time of safety inspection. Therefor the entire responsibility of the stability of the structure of the school building will be with the school administration.
3. Building repairing to be done every year. Safety of the school building from every corner is the full responsibility of the school.
4. This certificate is not for any legal purpose.
5. The undersigned can inspect the school any time during the session 2026-27. The Building Safety Certificate can be cancelled, if any discrepancy is found.
6. According to the National Building Code regulations, all necessary provisions for building safety must always be in ready to use by the school administration, of which the school administration has been informed during inspection. Therefore, the complete responsibility for compliance with the provisions will rest with the school administration.

Issued on 03/08/2026 at Camp Office, Dhoran Dehradun by

Signature with Seal:

Name: SANDEEP SEMWAL

Sub Divisional Engineer

Temporary Division PWD Rishikesh, Dehradun

अरवि चन्द, सोनीवाला
अरवि चन्द, सोनीवाला
अरवि चन्द, सोनीवाला